

Application Success Story:

Industry: Food Processing Product: Corn Mash Sealing Solution: Mechanical Seal



Equipment Info

- Worthington Pump
- Model D1011 FRAME 3
 - 1.750" (44.45mm) sleeve
 - 2.500" (63.50mm) bore

Problem

- Excessive flush at
 - 5-15 GPH / *19 56 LPH*
- High maintenance costs
- Short seal life
- Solution
 - SpiralTrac[™] Version D
 Type I installed with a 155
 mechanical seal
 - Now operating with no flush and no leakage
 - Lasting at least 9 months with no problems
 - Dramatically increased MTBR
 - Dramatically decreased operating and maintenance costs
 - Customer very happy



2456 Rocky Lake Drive Waverley, Nova Scotia, B2R 186 CANADA

Waverley, Nova Scotia B2R 1R6 CANADA (902) 861-3464 Fax: (902) 861-3522 Email: sales@enviroseal.ca Website: www.enviroseal.ca DISTRIBUTED BY: