


Application Success Story:

Industry: Pulp & Paper

Product: Thick Stock

Sealing Solution: Packing



Canron K5 thick stock

11% stock

Problem

- Excessive leakage causing bearing failure
- Poor packing life
- Excessive flush
- High maintenance costs

Solution

- SpiralTrac[™] Version P Type S installed with 1730 Packing
- Flush reduced to a controlled drip rate leakage
- Dramatically increased MTBR
- Dramatically decreased operating and maintenance costs
- One plant has converted 5 pumps: 20 stuffing boxes
- Customer very happy



Equipment Info

 $-150^{\circ} \, \mathrm{F}$

- 500 rpm

pump

2456 ROCKY LAKE DITIVE
Waverley, Nova Scotia B2R 1R6 CANADA
(902) 861-3464 Fax: (902) 861-3522
Email: sales@enviroseal.ca
Website: www.enviroseal.ca

DISTRIBUTED BY:

