

Application Success Story:

Industry: Mining


Product: Coal Slurry

Sealing Solution: Mechanical Seal



Problem

- Excessive erosion
- VERY tough application
- Packing had to be replaced every two months
- Poor housekeeping



Solution

- SpiralTrac[™] Version N
 Type A installed with a
 Chesterton 442 split
 mechanical seal
- SpiralTrac and mechanical seal combination lasted at least ten times longer

Equipment info

- Warman 4/3 EHH in series
- Coal Prep
 - 33% slurry with magnetite



DISTRIBUTED BY:

