

Application Success Story:

Industry: Mining Product: Iron Ore Sealing Solution: Mechanical Seal





Equipment Info

Allis Chalmers SRL 5x4

Problem

- 20-30% slurry
- Very tough application
- Excessive leakage and wear with packing
- 24 GPM / 90 LPM flush rate
- High maintenance costs

Solution

- SpiralTrac[™] Version N
 type A installed with a
 155 mechanical seal
- Greatly reduced flush and leakage
- Improved MTBR
- Improved housekeeping



Engineering Products Limited 2456 Rocky Lake Drive Waverley, Nova Scotia B2R 1R6 CANADA (902) 861-3464 Fax: (902) 861-3522 Email: sales@enviroseal.ca Website: www.enviroseal.ca

EnviroSeal

DISTRIBUTED BY: