



# **Application Success Story:**

**Industry: Manufacturing** 

**Product: Bone Meal** 

Sealing Solution: Mechanical Seal





## Application Info

Durco MK III GR II

#### Problem

- Very tough application
- Very abrasive product
- Seals were lasting 2 months at best
- Possibility of flush water entering
- the productHigh maintenance costs

### Solution

SpiralTrac<sup>™</sup> Version N Type I installed with a Chesterton 180 seal

### Result

Now running flush free for a year



Website: www.enviroseal.ca

Waverley, Nova Scotia B2R 1R6 CANADA (902) 861-3464 Fax: (902) 861-3522 Email: sales@enviroseal.ca

DISTRIBUTED BY:

