


# **Application Success Story:**

Industry: Pulp & Paper

Product: Pulp Sealing Solution: Packing



## Application Info

- Lightnin Mixer

#### Problem

- Shaft worn badly
- Excessive Flush
- Excessive Product Leakage
- \$8000.00 to replace shaft
  and bearings plus downtime costs



#### Solution

 SpiralTrac<sup>™</sup> Seal Adaptor designed to move the packing to an area of the shaft with less wear and 3 rings of Chesterton high quality packing

### Result

- Doubled the life of the shaft
  at only 1/8 of the cost of a new one
- Now only Clean Leakage at the gland



Waverley, Nova Scotia B2R 1R6 CANADA (902) 861-3464 Fax: (902) 861-3522 Email: sales@enviroseal.ca Website: www.enviroseal.ca



DISTRIBUTED BY: